



Date of Issue: 1 November 2016

# Image Floor Sealer

## 1. IDENTIFICATION OF MATERIAL AND SUPPLIER

<b>Product Name</b>	Image Floor Sealer
<b>Code</b>	50110
<b>Product Use</b>	Floor Sealer
<b>Company Name</b>	Dominant (Australia) Pty Ltd
<b>Address</b>	12 Coglin Street, Brompton SA 5007, Australia
<b>Telephone</b>	1300 789 852 or +61 (8) 8245 6900
<b>Facsimile</b>	+ 61 (8) 8340 1626
<b>Emergency Phone</b>	13 11 26

## 2. HAZARDS IDENTIFICATION

<b>GHS Classification</b>	<b>Toxic to Reproduction 2</b>
<b>Signal Word</b>	<b>WARNING</b>
<b>Hazard Statements</b>	<b>Suspected of damaging fertility or the unborn child</b>
<b>Precautionary Statements</b>	Keep out of reach of children Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required.  IF exposed or concerned: Get medical advice/ attention.  Store locked up. Dispose of contents/container in accordance with state regulations
<b>Pictograms</b>	



## 3. COMPOSITION/INFORMATION ON INGREDIENTS

Ingredients	Name	CAS	Proportion
	2-(2-methoxyethoxy)ethanol	111-77-3	10 – 30%
	Ingredients determined not to be hazardous	Not required	Balance

Date of Issue: 1 November 2016

**Product name: Image Floor Sealer****4. FIRST AID MEASURES**

<b>Ingestion</b>	If swallowed do NOT induce vomiting. Immediately wash out mouth with water. Seek medical attention if symptoms persist.
<b>Eye</b>	If in eyes, hold eye lids apart and flush the eye continuously with running water for at least 15 minutes. Seek medical attention if irritation persists.
<b>Skin</b>	If skin contact occurs rinse off with water.
<b>Inhaled</b>	Not normally a problem due to method of use. However if breathing is affected move to fresh air. If problem persists seek medical attention.
<b>First Aid Facilities</b>	An eye wash and general washing facility should be available adjacent to the work area.
<b>Advice to Doctor</b>	Treat symptomatically. For advice contact a Poisons Information Centre. (Phone Australia 13 11 26; New Zealand 0800 764 766)

**5. FIRE FIGHTING MEASURES**

<b>Extinguishing Media</b>	Use appropriate extinguishing media to suit surrounding area
<b>Hazards from Combustion</b>	Material does not burn.
<b>Precautions for Fire Fighters</b>	Wear chemical splash suit and SCBA.
<b>Hazchem</b>	None assigned for product

**6. ACCIDENTAL RELEASE MEASURES**

<b>Emergency Procedures</b>	Keep unauthorized people away. Do not touch or walk through spilled material.
<b>Clean Up</b>	Spills will be slippery so treat promptly. If allowed to dry the product will form a deposit that may be difficult to remove. For minor spills mop up and rinse with water. For larger spills absorb on mineral absorbent material or absorbent pads. Place in plastic bags and put into bin. Rinse area with water.

**7. HANDLING AND STORAGE**

<b>Handling</b>	Wear appropriate protective clothing to prevent skin and eye contact. Use in well ventilated area. Keep containers closed when not in use. Maintain a high standard of personal hygiene. Wash hands immediately after using product.
<b>Storage</b>	Store in a cool, dry, well ventilated place out of direct sunlight. Keep container closed.

Date of Issue: 1 November 2016

**Product name: Image Floor Sealer****8. EXPOSURE CONTROLS / PERSONAL PROTECTION**

<b>Exposure Standards</b>	No exposure standards are listed for the product
<b>Engineering Controls</b>	Use in well ventilated area.
<b>Personal Protective Equipment</b>	Wear rubber or chemical resistant gloves when using product. If decanting wear gloves and goggles.

**9. PHYSICAL AND CHEMICAL PROPERTIES**

<b>Appearance</b>	Milky white emulsion with mild acrylic odour
<b>Solubility in Water</b>	Soluble in all proportions
<b>pH</b>	9.0
<b>Flash Point</b>	Non flammable
<b>Melting Point</b>	Not available
<b>Boiling Point</b>	Not available
<b>Specific Gravity</b>	1.040

**10. STABILITY AND REACTIVITY**

<b>Stability</b>	Stable under normal conditions
<b>Hazardous Polymerisation</b>	Will not occur
<b>Conditions to Avoid</b>	Keep container closed to prevent it forming a film on the surface.
<b>Incompatible Materials</b>	Do not mix with other chemicals as the emulsion may coagulate.

**11. TOXICOLOGICAL INFORMATION**

<b>Ingestion</b>	May result in nausea, vomiting and diarrhoea.
<b>Eye</b>	The product is irritating to eyes causing smarting, pain and redness.
<b>Skin</b>	Contact with skin may result in irritation, redness and itching.
<b>Inhalation</b>	Not a volatile product
<b>Chronic Effects</b>	Prolonged or repeated exposure to this product may result in skin irritation and possibly result in dermatitis.
<b>Toxicological Data</b>	None available for product. However for ingredients... 2-(2-methoxyethoxy)ethanol Eye-rbt 500 mg MOD Orl-rat LD50: 9210 mg/kg (Source: Dangerous properties of industrial materials, 7 <sup>th</sup> Ed.)

Date of Issue: 1 November 2016

**Product name: Image Floor Sealer****12. ECOLOGICAL INFORMATION**

**Ecotoxicity** No information available. Avoid contaminating waterways.

**13. DISPOSAL CONSIDERATIONS**

Product may be disposed of to sewer. If residues are disposed of to sewer flush with plenty of water to dilute. Do not allow to enter stormwater system

**14. TRANSPORT INFORMATION**

<b>UN No.</b>	None allocated
<b>Proper Shipping Name</b>	None allocated
<b>Hazchem Code</b>	None allocated
<b>Class</b>	None allocated
<b>Packing Group</b>	None allocated

**15. REGULATORY INFORMATION**

**Classification** Poisons Schedule: Not classified according to the Poisons Standard March 2016

Hazardous according to the criteria of the Globally Harmonised System of Classification and Labelling of Chemicals (GHS).

**16. OTHER INFORMATION**

**Contact Point** Dominant Australia. Phone 08 8245 6900  
24 hour medical emergency 13 11 26

**Date of preparation** 1<sup>st</sup> November 2016